

## *Lumber Smith Sawmill*

### *Applying Scale Tape to the Legs*

The scale tape should be applied to the outside of the 2 legs. Look from the top of the leg and you will see the case has a 3 degree offset where the leg goes. Put the tape in the 3 degree gap - on the outside of the leg toward the motor side. Here's what to do:

- Remove the double wheel leg.
- Cut 1 roll of tape to 24".
- Apply this tape to the outside of the double wheel leg, toward the motor side of the saw with the 24" mark of the tape at the top of the leg...extending down.
- Put the double wheel leg back on the saw.
- Level your track.
- Put the saw on the track.
- Raise or lower the saw on the double wheel side to 16".
- Level the saw with the single wheel leg. Use the torpedo level placed on the blade or top of the case.
- When the saw is level, mark the single wheel leg. This will be the 16" position of the second roll of tape.
- Remove the single wheel leg and apply the tape to the outside of the leg toward the motor side of the leg aligning the tape's 16" mark to your mark on the leg.
- Cut the unused portion of the scale tape at the top of the single wheel leg.
- Replace the single wheel leg.

The photo below shows the single wheel leg after the scale tape is applied at the 16" mark. You can see the mark made on the leg when the saw was leveled. Note the scale tape is applied toward the motor side of the saw.

